

N.Venkata Ramana Rao
Structural Engineer.


vee aar
Architects And Engineers
A.S.Rao Nagar, Kapra, Hyd.

RC NO: 863/HYD/2023

STRUCTURAL STABILITY CERTIFICATE

1. I have inspected the **Mount Litera Zee School Building** in **Survey No: 58 & 59**, Situated at Yellareddyguda, , Kapra Mandal, Medchal Malkajgiri District, and found that the Building has Ground and Three upper Floor i.e., Total Four Floors only and the Height of the Building under consideration is 12.00 meters.

The **Mount Litera Zee SCHOOL** is Represented by its Secretary & Correspondent **Smt. T. Rama Devi.**

2. I have thoroughly inspected the said Building and found that no adverse indications about the structural weakness or impairment in the Building.

3. I therefore hereby certify that the said building is Structurally safe and Structurally Sound as on date for running **the School for the Academic year 2023-2024.**



N. Venkata Ramana Rao
Lic. No. 19/Str. Engineer/TP10/GHMC/2019-24
Plot No 2, G Block, A.S Rao Nagar, Kapra, Hyd



MANDAL EDUCATIONAL OFFICER
U.P. KEESARA, MEDCHAL DIST.

Date: October 4, 2023

Signature of The Structural Engineer
(N.VENKATA RAMANA RAO)